



Mar 2025

WATS Feature Release Note
Test step analysis – 25.1 - R2



Major Feature Areas

- New Features – Details view 3
 - Loop Iteration Filtering..... 3
 - Statistics Tab..... 3
 - Enhanced Individuals Charts 4
- Enhancements – Step details 4
 - Improved Charting Experience 4
- User Experience Improvements 4




New Features – Details view

The new *Test step analysis* is now out of preview. *Test step yield & analysis* and *Process capability analysis* is marked as legacy and will be discontinued in a later version.


Loop Iteration Filtering

- A loop iteration control has been added to the Workbench ribbon, allowing users to analyse measurements made at any iteration of a **looped step**. This only applies for the Individuals data view.



Statistics Tab


- A new statistics tab has been introduced in the Workbench sidebar, displaying key measurement statistics for each analysed step.
 - Statistics will be recalculated based on custom limits and min/max filtering set in the ribbon toolbar.



STATISTICS	
Measurement #	946
Max	0.74
Avg	0.68
Min	0.01
Sum	645.31
High limit	1.05
Low limit	0.50
Cpk	0.55
Cp	0.83
Cp upper	1.11
Cp lower	0.55
Stdev	0.11
Var	0.01

Enhanced Individuals Charts

- **Type-specific y-axes:** The measurement value series of each analysed step will now display datapoints on axes appropriate to their step type.
 - Numeric measurements on a numerical y-axis.
 - String value measurements on a y-axis listing all occurring string values.
 - Pass/fail measurements on a y-axis with boolean value.
 - The measurement value series of steps without measurement values will plot the step status on a y-axis listing all status values.



Enhancements – Step details

Improved Charting Experience

- Additional series has been added to the aggregated chart in the workbench view:
 - High / Low limit
 - Sum
 - Max / Avg / Min step execution time
- Alt key box zoom functionality has been added to all charts.
- Axes without visible series are hidden, providing a cleaner user interface.
- Empty charts are replaced with user messages noting that the queried dataset is empty.

User Experience Improvements

- UUT reports opened from the Step chart view will automatically scroll to and highlight associated steps.



- The Step Details link in UUT reports has been updated to direct users to the new Step Details module.
- Settings and visibility of series is now maintained per session in the workbench and step chart views.